



Walcowe zaokrąglone

A



| | | | | | | | | | | | |
|---------------|---------|---------|----------|-----------|-----------|-----------|---------|---------|-----------|---------|---------|
| d1 mm | 2.5 | 3 | 3 | 3 | 4 | 5 | 6 | 6 | 6 | 8 | 10 |
| l1 mm | 11 | 13 | 13 | 13 | 16 | 16 | 13 | 19 | 25 | 19 | 19 |
| d2 mm | 3 | 3 | 3 | 3 | 6 | 6 | 3 | 6 | 6 | 6 | 6 |
| l2 mm | 38 | 38 | 50 | 75 | 50 | 50 | 45 | 50 | 50 | 65 | 65 |
| s | GT3100S | GT3200S | - | - | GT3300S-6 | - | GT3240S | GT3400S | - | GT3500S | GT3600S |
| d | GT3100D | GT3200D | GT3200DL | GT3200DXL | GT3300D-6 | GT3350D-6 | GT3240D | GT3400D | GT3400D-1 | GT3500D | GT3600D |
| d-max | - | - | - | - | - | - | - | - | - | GTDX350 | GTDX360 |
| c | - | GT3200C | - | - | - | - | - | GT3400C | - | - | GT3600C |
| k | - | GT3200K | - | - | GT3300K-6 | - | - | GT3400K | - | GT3500K | GT3600K |
| alu | - | - | - | - | - | - | - | GTTA340 | - | - | GTTA360 |
| RAPIDE | | | | | | | | | | | |
| d | - | - | - | - | - | - | - | CZ3400D | - | - | CZ3600D |
| d-max | - | - | - | - | - | - | - | - | - | - | CZDX360 |
| alu | - | - | - | - | - | - | - | - | - | - | CZTA360 |



| | | | | | | | |
|---------------|-----------|---------|---------|-----------|-------------|-----------|---------|
| d1 mm | 10 | 11 | 12 | 12 | 12 | 16 | 16 |
| l1 mm | 25 | 25 | 19 | 25 | 25 | 25 | 25 |
| d2 mm | 6 | 6 | 6 | 6 | 8 | 6 | 8 |
| l2 mm | 70 | 70 | 65 | 70 | 70 | 70 | 70 |
| s | - | - | GT3700S | GT3700S-1 | GT3700S-1-8 | GT3800S-6 | GT3800S |
| d | GT3600D-1 | GT3650D | GT3700D | GT3700D-1 | GT3700D-1-8 | GT3800D-6 | GT3800D |
| d-max | - | - | GTDX370 | GTDX370-1 | GTDX370-1-8 | GTDX380-6 | GTDX380 |
| c | - | - | GT3700C | GT3700C-1 | - | - | - |
| k | - | - | GT3700K | GT3700K-1 | - | - | - |
| alu | - | - | - | GTTA370 | - | - | GTTA380 |
| RAPIDE | | | | | | | |
| d | - | - | - | CZ3700D-1 | - | - | - |
| d-max | - | - | - | CZDX370-1 | - | - | - |
| alu | - | - | - | CZTA370 | - | - | - |